BL/TZ INFORMATION

No. 2015-0054EN 2015/3/2 Blitz Co., Ltd.


New Product Information



- Actuator type Metal Follow Turbine for 86/BRZ Turbo System.
- Around 260PS with 300N m torque
 (Normal engine is modified by Blitz setting)
- BLITZ original B06-380R turbine is used.
- Turn-buckle type actuator is equipped.
- 4 different type of kits are available.



POWER CHECK SHEET



★Boost setting is 0.5hkPa with B-EMU.

XPower check is measured by Blitz chassis dynamometer.

Power check result may be different of measurement equipment and ECU setting.

Release Date: On Sale Now!

http://www.blitz.co.jp/

BL/TZ INFORMATION

B06-380R Turbo Spec								
Name	Maximum corresponding horse power	Compressor Wheel			Turbine Wheel			
		trim	In Dia(mm)	Ex Dia(mm)	trim	In Dia(mm)	Ex Dia(mm)	
B06-380R	380PS	60.7	53	68	76.6	56	49	

Product Information								
Product Name	Catalyzer	ECU	Boost Controller	MSRP w/tax	MSRP	Code No.	JAN Code	
TURBO SYSTEM 86/BRZ W/O CATA				¥399,600	¥370,000	10203	4959094102038	
TURBO SYSTEM 86/BRZ TUNRERS KIT	Include			¥399,600	¥370,000	10202	4959094102021	
TURBO SYSTEM 86/BRZ STARTUP KIT	Include	W/ B-EMU		¥464,400	¥430,000	10201	4959094102014	
TURBO SYSTEM 86/BRZ FULL KIT	Include	W/ B-EMU	W/SBC TypeS	¥486,000	¥450,000	10200	4959094102007	

- START UP KIT and FULL KIT are NOT available for overseas.
- Option parts (sold separately)

TURBO SYSTEM 86/BRZ needs to install the welding processed oil pan.



Product Information						
Product Name	MSRP w/tax	MSRP	Code No.	JAN Code		
Welding processed oil pan for 86/BRZ	¥21,600	¥20,000	10186	4959094101864		

Vehicle Information							
Vehicle	Model Year	Model	E/G Model	Transmission	Remarks		
86	2012/04-	ZN6	FA20	MT, AT			
BRZ	2012/03-	ZC6	FA20	MT, AT			

XTurbo kit is NOT covered by warranty for overseas.

This product improves the output of the engine power; therefore, durability of vehicle will be decreased.

There is no warrantee for the parts of vehicle.

This product has to have ECU setting.

You have to do ECU setting by yourself.

This product needs some modifications in order to install for overseas model, such as different side steering wheel.